

20(125)/ज०के०म००.१/२०१२/ 660

दिनांक: 4-2-12

The Principal,
Kendriya Vidyalaya No. 1,
Gole Market, Hospital Road,
Gandhi Nagar, Jammu

प्रयः

Safety and Security Certificate of Kendriya Vidyalaya Building.

दिर्भः

Your office letter No. F-32/KVJ-1/2011/783 dated 25-01-2012.

With reference to letter cited above, it is intimated that the above cited School Building was inspected on last month by the Assistant Engineer-IV of this Division alongwith the worthy Principal of the said school and members of M&R committee of the school and following observation is made:-

The overall school building is found structurally safe as per visual inspection and it is also observed that at some places the cracks were found in beams, chajjas & wall junctions which needs immediate proper bonding. At terrace grass has been grown up over the cracks & needs immediate regrading with Coba treatment to avoid seepages in rainy season in future. Some ceiling plaster also needs immediate repair.

नमोनाम अधिका,
 जय केन्द्रीय विद्यालय नं० १,
 गोलामार्कट रोड